ASBESTOS ASSES

SURVEY

H-K Building #: 21

Project Number: 0980193E
Project: G. HEILEHAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

LOCATION OF THE MATERIAL	SAMPLE Number	ASB	MATERIAL DESCRIPTION	CODE	QUANTITY	UNITS OF MEASURE		EXP POT P	REHOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
above caustic tank & along east wall	00-356573	25%	pipe covering	OMA	50 1	ft. 4 in. O.D.	HPS/R	27 II	\$446	\$279	\$7
southeast area-by caustic tank	00-356577	0%	pipe covering	OHA	30 1	ft. 8 in. O.D.	DW				
above caustic tank & along south wall	00-356581	10%	wrapped cardboard/paper pipe	OHA	42 1	ft. 8 in. 0.D.	DW	27 11	\$594	\$425	\$1,0
center E to W-along beam-at ceiling	00-356585	15%	urapped cardboard/paper pipe	OHA	25 1	ft. 6 in. 0.D.	DW	27 11	1 5324	\$203	\$
along east wall-near ceiling	00-356585	15%	urapped cardboard/paper pipe	OHA	70 1	ft. 4 in. O.D.	DW	27 11			\$1,0
near north entrance	00-356585	15%	wrapped cardboard/paper pipe	AMO	26 1	ft. 8 in. 0.D.	₽₩	27 11			\$6
above caustic tank & along east wall	00-356585		wrapped cardboard/paper pipe	OKA	30 1	ft. 4 in. 0.D.	DW	27 11			\$4
center N to S-along beam-at ceiling	00-356585		wrapped cardboard/paper pipe	OHA		ft. 4 in. O.D.		27 11			\$1
above caustic tank & along east wall	12-356574		mjp on pipe covering	OHA	20 4	4 in. O.D.	HPS/R			\$312	\$1
	12-356575	10%	1					27 11			
	12-356576	25%	•			•		27 11		-	
southeast area-by caustic tank	13-356578		mjp on pipe covering	OHA	3 8	B in. O.D.	DW	27 11		\$85	\$
	13-356579	0%						27 11			
	13-356580	0%	1					27 11			•
above caustic tank & along south wall	14-356582	35%	mjp on wrapped cardboard/paper	OMA	70* 8	B in. O.D.	DM	27 11		\$1,981	\$5,3
	14-356583	40%	1					27 11			
	14-356584	50%	ł .					27 11			
near north entrance	15-356586		mjp on wrapped cardboard/paper	AHO	2 (8 in. O.D.	DW	27 11	1 \$96	\$57	\$
along east wall-near ceiling	15-356586		mjp on wrapped cardboard/paper	OHA	10 4	4 in. O.D.	DW	27 11			• \$
above caustic tank & along east wall	15-356586		[mjp on wrapped cardboard/paper		6 (4 in. O.D.	₽₩	27 11	I \$169		· \$
center E to W-along beam-at ceiling	15-356586		mjp on wrapped cardboard/paper		1 (6 in. O.D.	₽₩	27 11			
center N to S-along beam-at ceiling	15-356586		mjp on wrapped cardboard/paper	OHA	1 4	4 in. O.D.	DW	27 11		\$16	
	15-356587	60X	į.					27 [1			
	15-356588	60%						27 11			

AREA COMMENTS

AREA # 01 TOTAL \$7,419 \$4,519 \$11,938

AREA AVERAGE % ASBESTOS: 27%

The materials are in fair condition with minor localized contact and water damage. The materials are approximately 5' to 14' from the floor. At a minimum, it is recommended that the materials be properly repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a medium traffic area.

AREA DESCRIPTION: Ground Floor

_	· · · · · · · · · · · · · · · · · · ·								 			
	LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&H CODE	QUANTITY	UNITS OF HEASURE	PIPE ID	 PL	REHOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
	part 21-brew kettle rm-under S kettle part 21-brew kettle rm-under S kettle	00-356573 00-356573		pipe covering	AHO AHO		t. 4 in. 0.D. t. 6 in. 0.D.				\$446 \$41	\$1,160 \$106

HALL-KIMBRELL ENVIRONMENTAL INC.

AREA NUMBER: 02

Page 44

06/09/89

H-K Building ____21 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89
Inspector: TIM SWARTZ

Building Number: 21/22 Building Number: 21/22
Building Name: BREWHOUSE/STOCK CELLARS
SEATTLE, WASHINGTON
Building Type: BREW/STOCK
Year Constructed: 1948

Inspector: I'm Swartz					1	rear Cor	istructed:	1948		
part 21-west wall	00-356573	25%	pipe covering	OHA	20 ft, 6 in, O.D.	HPS/R	26 1111	\$260	\$162	\$422
stairwell in part 21	00-356573		pipe covering	OHA	5 ft. 4 in. 0.0			\$45	\$28	\$73
stairwell in part 21	00-356573		pipe covering	OMA	3 ft. 6 in. O.D			\$39	\$24	\$63
part 21-brew kettle rm-under N kettle	00-356573		pipe covering	OHA	45 ft. 4 in. O.D.			\$401	\$251	\$652
part 21-brew kettle rm-under N kettle	00-356573		pipe covering	OHA	16 ft. 6 in. O.D			\$208	\$130	\$338
part 21-against south wall-along ceiling	00-356573		pipe covering	OHA	20 ft. 4 in. 0.0			\$178	\$112	\$290
part 21-brew kettle rm-along east wall	00-356573		pipe covering	OHA	45 ft. 4 in. O.D			\$401	\$251	\$652
part 22-cellar H stock-along east wall	00-356573		pipe covering	OHA	180 ft. 4 in. O.D			\$1,606	\$1,004	\$2,610
part 22-cellar H stock-along east wall	00-356573		pipe covering	OHA	180 ft. 8 in. O.D			\$2,547	\$1,820	\$4,367
part 21-west wall	00-356573	25%	pipe covering	OMA	40 ft. 8 in. O.D			\$566	\$404	\$970
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OHA	130 ft. 4 in. O.D			\$1,160	\$725	\$1,885
part 21-brew kettle room-catwalk	00-356573	25%	pipe covering	OHA	88 ft. 6 in. O.D			\$1,142	\$714	\$1,856
part 21-west wall	00-356573	25%	pipe covering	OHA	40 ft. 4 in. O.D			\$357	\$223	\$580
stairwell in part 21	00-356573	25%	pipe covering	OMA	3 ft. 10 in. 0.0	HPS/R	26 111	\$57	\$42	\$99
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577	0%	pipe covering	OHA	35 ft. 4 in. O.D	. DU	- 1			
pt 21-brew kettle rm-catwalk-ctr&E wall	00-356577	0%	pipe covering	OHA	10 ft. 6 in. O.D	. DW				1
part 21-against south wall-along ceiling	00-356577	0%	pipe covering	OHA	25 ft. 8 in. O.D		1			i i
part 21-brew kettle rm-northeast area	00-356589	40%	pipe covering	OHA	25 ft. 6 in. O.D	. PL -	26 111	\$324	\$203	\$527
part 21-brew kettle rm-kettle at N end	01-356463	50%	boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448.	\$18,783	\$42,231
	01-356464	35%			•		26 111	•	•	· 1
	01-356465	35%					26 111			•
part 21-brew kettle rm-kettle at S end	02-356466		boiler/tank insulation	OMB	830 sq.ft.		26 111	\$23,448	\$18,783	\$42,231
	02-356467	40%			•		26 111	-	•	,
	02-356468	40%					26 111			į
part 21-brew kettle room-catwalk	12-356574		mjp on pipe covering	OHA	16 4 in. O.D.	HPS/R	26 111	\$449	\$250	\$699
part 22-cellar H stock-along east wall	12-356574		mjp on pipe covering	AHO	4 8 in. O.D.	HPS/R	26 111	\$193	\$113	\$306
part 21-brew kettle rm-under S kettle	12-356574		mjp on pipe covering	OHA	20 4 in. O.D.	HPS/R	26 111	\$562	\$312	\$874
part 21-west wall	12-356574		mjp on pipe covering	OMA	5 4 in. O.D.	HPS/R	26 111	\$140	\$78	\$218
stairwell in part 21	12-356574		mjp on pipe covering	OHA	1 10 in. O.D.		26 111	\$63	\$39	\$102
part 22-cellar H stock-along east wall	12-356574		mjp on pipe covering	OMA	4 4 in. O.D.	HPS/R	26 111	\$112	\$62	\$174
part 21-against south wall-along ceiling	12-356574		mjp on pipe covering	OMA	4 4 in. O.D.	HPS/R	26 111	\$112	\$62	\$174
part 21-brew kettle rm-under N kettle	12-356574		mjp on pipe covering	OHA	15 4 in. O.D.	HPS/R	26 111	\$421	\$234	\$655
part 21-west wall	12-356574		mjp on pipe covering	OHA	4 8 in. O.D.	HPS/R	26 111	\$193	\$113	\$306
part 21-brew kettle room-catwalk	12-356574		mjp on pipe covering	OHA	20 6 in. O.D.	HPS/R	26 111	\$774	\$454	\$1,228
stairwell in part 21	12-356574		mjp on pipe covering	OMA	1 6 in. O.D.	HPS/R	26 111	\$39	\$23	\$62
stairwell in part 21	12-356574		mjp on pipe covering	OMA	1 4 in. O.D.	HPS/R	26 111	\$28	\$16	\$44
part 21-brew kettle rm-along east wall	12-356574		mjp on pipe covering	OHA	10 4 in. O.D.	HPS/R	26 111	\$281	\$156	\$437
part 21-west wall	12-356574		mjp on pipe covering	OHA	8 6 in. O.D.	HPS/R	26 111	\$309	\$182	\$491
	12-356575	10%					26 111			1
	12-356576	25%					26 111			. [
pt 21-brew kettle rm-catwalk-ctr&E wall	13-356578		mjp on pipe covering	OHA	8 4 in. 0.0.	DW	26 111	\$225	\$125	\$350
part 21-against south wall-along ceiling	13-356578	4 0%	mjp on pipe covering	OMA	2 8 in. O.D.	DU	26 111	\$96	\$57	\$153
·	13-356579	0%	,				26 111	5		
	13-356580	0%	· ·				26 111		. *	-
part 21-brew kettle rm-northeast area	16-356590		mjp on pipe covering	ONA	12 6 in. 0.D.	PL	26 111	\$464	\$273	\$737
	16-356591	0%	1				26 111			
	16-356592	40%	l				26 111			
part 21-brew kettle rm-caustic tank	17-356593	0%	boiler/tank insulation	OMB	90 sq.ft.				•	
·		•			- 1					

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 45

ASBESTOS ASS.

H-K Building..... 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS SEATTLE, WASHINGTON Building Type: BREW/STOCK

Year Constructed: 1948

		18-356598	40%	<u> </u>	······································			26.111			
	part 21-brew kettle rm-3M CIP tank-north	18-356596 18-356597	40% 50%	boiler/tank insulation	OMB	86 sq.ft.	•	26 111	\$2,430	\$1,946	\$4,376
		17-356595	0%					i i			
_		17-356594	0%								

The materials are in fair to good condition with minor contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

******** AREA NUMBER: 03	AREA DESC	RIPTIC	ON: 2nd Floor-Part #21 ,		AREA AVERAGE	% ASBE	stos:	35X	*****	***
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL COSTS	REPLACEMENT COSTS	TOTAL COSTS
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OHA	20 ft. 4 in. 0.D	. HPS/R	26 1	11 \$171	\$112	\$290
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	AHO	8 ft. 10 in. 0.1	HPS/R	26	11 \$15	\$112	\$263
stairwell between 1st & 2nd floors	00-356472	30%	pipe covering	OHA	8 ft. 12 in. 0.1	HPS/R	26	11 \$176	\$ \$135	\$311
kettle room-north area	00-356472	30%	pipe covering	OHA	- 140 ft. 4 in. O.D	. HPS/R	26	11 \$1,249	\$781	\$2,030
kettle room-north area	00-356472	30%	pipe covering	AHO	16 ft. 6 in. 0.D	. HPS/R	26	11 \$208	\$130	\$338
kettle room-north area	00-356472	30%	pipe covering	AHO	15 ft. 8 in. O.D	. HPS/R	26 1	11 \$217	\$152	\$364
kettle room-mezzanine-along south wall	00-356472	30%	pipe covering	AHO	10 ft. 12 in. 0.0	HPS/R	26	11 \$220	\$169	\$389
kettle room-mezzanine-along north wall	00-356472	30%	pipe covering	OHA	5 ft. 6 in. 0.D	. HPS/R	26 1	11 \$65	s41	\$106
kettle room-hops storage	00-356472	30%	pipe covering	AHO	40 ft. 4 in. 0.0	. HPS/R	26	\$357	s223	\$580
kettle room-mezzanine-along south wall	00-356472	30%	pipe covering	OHA	10 ft. 10 in. 0.1	D HPS/R	26	11 \$189	\$140	\$329
kettle room-mezzanine-along north wall	00-356472	30%	pipe covering	OHA	30 ft. 8 in. O.D	. HPS/R	26	11 \$424	\$303	\$727
kettle room-mezzanine-against east wall	00-356472	30%	pipe covering	OHA	18 ft. 8 in. O.D	. HPS/R	26	11 \$259	\$182	\$437
kettle room-mezzanine-against south wall	00-356476	40%	wrapped cardboard/paper pipe	OHA	10 ft. 8 in. O.D	. DU	26	LI \$14	\$101	\$242
kettle room-break room	00-356476	40X	wrapped cardboard/paper pipe	OHA	1 ft. 6 in. 0.D	. DW	26	11 \$1:	\$ \$8	\$2
kettle room-break room	00-356476	40%	wrapped cardboard/paper pipe	OHA	10 ft. 8 in. O.D		26			\$242
kettle room-hops storage-northeast area	00-356476	40%	wrapped cardboard/paper pipe	OHA	10 ft. 6 in. O.D	. DW	26	11 \$130	\$81	\$21
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OHA	6 4 in. 0.D.	HPS/R	26			- \$263
kettle room-north area	04-356473		mjp on pipe covering	AHO	4 6 in. O.D.	HPS/R			\$91	\$246
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OHA	2 10 in. O.D.	HPS/R				\$203
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OMA	6 6 in. O.D.	HPS/R				\$368
kettle room-mezzanine-along north wall	04-356473	50%	mjp on pipe covering	OHA	5 8 in. O.D.	HPS/R				\$382
stairwell between 1st & 2nd floors	04-356473	50%	mjp on pipe covering	OMA .	2 12 in. O.D.	HPS/R				\$24
kettle room-north area	04-356473	50X	mjp on pipe covering	OMA	12 4 In. O.D.	HPS/R				\$52
kettle room-hops storage-south area	04-356473	50%	mip on pipe covering	OHA	12 4 in. O.D.	HPS/R				\$52
kettle room-north area	04-356473	50%	mjp on pipe covering	OHA	3 8 in. O.D.	HPS/R				\$22
kettle room-mezzanine-against east wall	04-356473	50%	mjp on pipe covering	ONA	4 8 in. O.D.	HPS/R				\$30
	04-356474	50%					26			450
·	04-356475	60%					26			

HALL-KIMBRELL ENVIRONMENTAL INC.

ASBESTOS ASSE.

H-K Building *: 21 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89

Inspector: TIM SWARTZ

Building Number: 21/22

Building Name: BREVHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

231

<u>'</u>										07.
kettle room-break room	05-356477	60%	mjp on wrapped cardboard/paper	OHA	1 8 in. O.D.	DW	26 1111	\$48	\$28	\$76
kettle room-break room	05-356477		mjp on wrapped cardboard/paper		2 6 in. 0.D.	DW	26 111	\$77	\$45	\$122
	05-356478	50%	1				26 111			
	05-356479	50%	(•	••	26 111			
kettle room-break room-whirlpool	06-356480	50%	boiler/tank insulation	OMB	550 sq.ft.		26 111	\$15,538	\$12,446	\$27,984
·	06-356481	10%			•		26 111	·	•	•
•	06-356482	40%	ţ				26 111			
	<u></u>		<u> </u>							

AREA COMMENTS

AREA # 03 TOTAL \$21,857 \$16,497 \$38,354

The materials are in good condition with minor contact and water damage. The materials are approximately 1' to 18' from the floor. At a minimum, it is recommended the materials be repaired and monitored. If removal is planned, gross removal procedures are recommended. This appears to be a high traffic area.

******* AREA NUMBER: 04	AREA DESCI	RIPTIO	N: 3rd Floor-Part #21-Tank Bott	om Room	AREA AVERAGE % A	SBES	TOS: 327	<u> </u>	******	****
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE		PE D	EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL
below mash tub	00-356495	30%	pipe covering	OHA	55 ft. 4 in. O.D. HP	>S/R	28 111	\$491	\$307	\$798
below mash tub	, 00-356495	30%	pipe covering	OHA	35 ft. 6 in. O.D. HP	S/R	28 111	\$454	\$284	\$73
north of mash filter	00-356495	30X	pipe covering	OMA	6 ft. 4 in. O.D. HF	PS/R	28 111	\$54	\$33	\$8
south of mash filter	00-356495	30%	pipe covering	OHA	10 ft. 8 in. O.D. HF	PS/R	28 111	- \$141	\$101	\$24
below adjunct cooker	00-356495		pipe covering	OHA	25 ft. 10 in. 0.D HF	PS/R	28 111	\$472	\$349	\$82
below convertor tank	00-356495		pipe covering	ONA	30 ft. 6 in. O.D. HF	PS/R	28 111	\$389	\$243	\$63
Just northeast of caustic tank	00-356495		pipe covering	OHA	15 ft. 4 in. O.D. HF	PS/R	28 111		\$84	\$21
just northeast-of caustic tank	00-356495		pipe covering	OHA	. 5 ft. 6 in. O.D. HF		28 111	\$65	\$41	\$10
below convertor tank	00-356495		pipe covering	AHO	60 ft. 4 in. O.D. HF		28 111	\$535	\$335	\$87
below adjunct cooker	00-356495		pipe covering	OHA	55 ft. 6 in. O.D. HF		28 111	\$714	\$446	\$1,160
below adjunct cooker	00-356495		pipe covering	AHO	60 ft. 4 in. O.D. HF		28 111	\$535	\$335	\$870
behind caustic tank-against south wall	00-356495		pipe covering	OHA	16 ft. 8 in. O.D. HF	PS/R	28 111	\$226	\$162	\$38
behind caustic tank-against south wall	00-356499	20X	wrapped cardboard/paper pipe	AHO	8 ft. 8 in. O.D. HF	PS/R	28 111	\$113	\$81	\$19
center E to W-along beam-near ceiling	00-356603	30%	pipe covering	OMA	90 ft. 6 in. O.D. PL	L	28 111	\$1,168	\$730	\$1,89
east side-mash filter-near floor	00-356603		pipe covering	AHO	6 ft. 6 in. 0.D. Pl		28 111	\$78	\$49	\$12
east side-mash filter-near floor	00-356603	30%	pipe covering	OHA	6 ft. 4 in. O.D. Pl		28 111	\$54	\$33	\$8
east wall-near adjunct cooker-at floor	00-356603	30%	pipe covering	OHA	4 ft. 10 in. O.D Pl	L	28 111	\$75	\$56	\$13
below adjunct, convertor & mash tub tanks	00-356603	30%	pipe covering	AHO	60 ft. 10 in. 0.D PL	Ĺ	28 111	\$1,132	\$838	\$1,97
east wall-near adjunct cooker-at floor	00-356603	30X	pipe covering	OHA	22 ft. 6 in. 0.D. Pl	L	28 111	\$286	\$178	\$46
convertor tank	07-356483	35%	boiler/tank insulation	OMB	600 sq.ft.		28 111	\$16,950		\$30,52
1	07-356484	40%					28 111			
	07-356485	40%	1				28 111			
adjunct cooker	08-356486	40%	boiler/tank insulation	OMB	600 sq.ft.		28 111		\$13,578	\$30,52
	08-356487	40%					28 111		2.2,2.0	,
,	08-356488	40%					28 111			
mash tub	09-356489		boiler/tank insulation	OMB	600 sq.ft.		28 111		\$13,578	\$30,52
	09-356490	50%	Total A call Call Call Call Call	CITO	ood sq. 1 C.		28 111		+13,310	عد, بد

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 47

ASBESTOS ASSE SURVEY

H-K Building 21 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

The protection of the control of the			·							3080
caustic tank	09-356491 10-356492		boiler/tank insulation	OHB	500 sq.ft.		28 III 28 III	\$14,125	\$11,315	\$25,440
	10-356493	50% 50%					28 111			
below adjunct cooker	11-356496	40%	mjp on pipe covering	OHA	25 6 in. O.D.	HPS/R	28 111	\$967	\$568	\$1,535
below convertor tank	11-356496	40X	mjp on pipe covering	OHA	35 4 in. O.D.	HPS/R	28 111	\$983	\$546	\$1,529
Just northeast of caustic tank	11-356496	40%	mjp on pipe covering	OMA	2 6 in. O.D.	HPS/R	28 111	\$77	\$45	\$127
below mash tub	11-356496	40%	mjp on pipe covering	OMA	30 4 in. O.D.	HPS/R	28 111	\$843	\$468	\$1,311
below adjunct cooker	11-356496	40%	mjp on pipe covering	OHA	6 10 in. O.D.	HPS/R	28 111	\$376	\$235	\$611
just northeast of caustic tank	11-356496	40%	mjp on pipe covering	OMA	8 4 in. 0.D.	HPS/R	28 111	\$225	\$125	\$350
below adjunct cooker	11-356496	40%	mjp on pipe covering	, OHA	27 4 in. O.D.	HPS/R	28 111	\$758	\$421	\$1,17
south of mash filter	11-356496		mjp on pipe covering	OHA	2 8 in. O.D.	HPS/R	28 111	\$96	\$57	\$153
below convertor tank	11-356496	40%	mjp on pipe covering	OHA	5 6 in. O.D.	HPS/R	28 111	\$193	\$114	\$307
below mash tub	11-356496	40% 50%	mJp on pipe covering	OMA	14 6 in. O.D.	HPS/R	28 111	\$542	\$318	\$86
	11-356497	50%	1	•			28 111			
below adjunct, convertor & mash tub tanks	21-356604		mjp on pipe covering	OMA	10 10 in. O.D.	PL	28 111	\$626	\$391	\$1,01
center E to W-along beam-near ceiling	21-356604		mlp on pipe covering	OHA	10 6 in. O.D.	PL	28 111	\$387	\$227	\$61
east wall-near adjunct cooker-at floor	21-356604	60%	mjp on pipe covering	OHA	6 6 in. O.D.	PL	28 111	\$232	\$136	\$36
east wall-near adjunct cooker-at floor	21-356604	60X	mjp on pipe covering	OHA	2 10 in. O.D.	PL	28 111	\$125	\$78	\$20
•	21-356605	60%					28 111			
	21-356606	60%	1				28 111			

AREA COMMENTS

AREA # 04 TOTAL \$78,521 \$60,463 \$138,984

The materials are in fair condition with localized contact and water damage. The materials are approximately 1' to 10' from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

****** AREA NUMBER: 05	AREA DESCR	RIPTIO	W: 3rd Floor-Part #21-Tank Top	Room		AREA AVERAGE	% ASBE	stos:	30%	<u> </u>	*****	***
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REHOVAL COȘTS	REPLACEMENT COSTS	TOTAL COSTS
north wall-by adjunct cooker	00-356495	30%	pipe covering	OHA	15 1	t. 4 in. 0.D	. HPS/R	27	111	`\$1 3 4	\$84	\$218
north wall-by adjunct cooker	00-356495	30%	pipe covering	OHA		t. 8 in. O.D				\$141	\$101	\$242
north wall-by adjunct cooker	00-356495	30%	pipe covering	OMA	10	ft. 12 in. O.	HPS/R	27	111	\$220	\$169	\$389
south wall-behind caustic tank	00-356495	.30%	pipe covering	OMA		ft. 6 in. O.D					\$243	\$63
south wall-behind caustic tank	00-356495	30%	pipe covering	OHA		ft. 4 In. O.D					\$56	\$14
south wall-behind caustic tank	00-356495	30%	pipe covering	OHA		ft. 10 in. O.					\$279	\$65
south wall-behind caustic tank	00-356499	20%	wrapped cardboard/paper pipe	OHA		ft. 10 in. O.			111		\$140	\$32
next to mash tub	00-356603		pipe covering	OHA		ft. 6 in. 0.D			iii			\$46
next to adjunct cooker	00-356603		pipe covering	ONA		ft. 6 In. O.D			iii			\$56
next to convertor tank	00-356603		pipe covering	OHA		ft. 6 in. 0.D			III			\$25
next to adjunct cooker	00-356603		pipe covering	OHA		ft. 8 in. 0.D			iii			\$60

HALL-KIMBRELL ENVIRONMENTAL INC.

ASBESTOS ASSE

SURVEY

H-K Building 21 Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS SEATTLE, WASHINGTON Building Type: BREW/STOCK Year Constructed: 1948

AREA COMMENTS						AREA # 05	TOTAL	\$6,955	\$4,387	\$11,3
	21-356606	60%					27 111	 		
	21-356605	60%					27 111			
next to convertor tank	21-356604	60%	mjp on pipe covering	OHA	4 6 in. O.D.	PL	27 111	\$155	\$91	\$2
next to mash tub	21-356604		mjp on pipe covering	OHA	12 4 in. O.D.	PL	27 111	\$337	\$187	\$5
next to adjunct cooker	21-356604			OMA	12 6 in. 0.D.	PL	27 111	\$464	\$273	\$7
next to convertor tank	21-356604		mjp on pipe covering	OHA	2 4 in. 0.D.	PL	27 111	\$56	\$31	. 1
next to mash tub	21-356604		mjp on pipe covering	OMA	8 6 In. 0.0.	PL	27 111	\$309	\$182	\$4
next to adjunct cooker	21-356604		mjp on pipe covering	OHA	8 8 in. 0.D.	PL	27 111	\$385	\$226	\$6
next to convertor tank	21-356604		mjp on pipe covering	OHA	6 4 in. 0.D.	PL	27 111	\$169	\$94	\$2
next to mash tub	21-356604		mjp on pipe covering	OHA	4 8 In. 0.D.	PL	27 111	\$193	\$113	\$3
next to mash tub	21-356604			OHA	6 8 in. 0.D.	PL	27 111	\$289	\$170	\$4
	20-356601 20-356602	60% 0%					27 111			
south wall-behind caustic tank	20-356600	70%	mjp on wrapped cardboard/paper	UMA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	90
	11-356498	50%				****	27 111	477/	e275	\$6
	11-356497	50%	1		•		27 111			
south wall-behind caustic tank	11-356496	40%	mjp on pipe covering	OHA .	2 6 in. 0.D.	HPS/R	27 111	\$77	\$45	\$1
north wall-by adjunct cooker	11-356496		mjp on pipe covering	AHO	1 8 in. O.D.	HPS/R	27 111	\$48	\$28	\$
south wall-behind caustic tank	11-356496	40%	mjp on pipe covering	OHA	6 10 in. O.D.	HPS/R	27 111	\$376	\$235	\$6
south wall-behind caustic tank	11-356496			OHA	2 4 in. 0.D.	HPS/R	27 111	\$56	\$31	SI
north wall-by adjunct cooker	11-356496		mjp on pipe covering	OHA	5 4 in. 0.D.	HPS/R	27 [1]	\$140	\$78	\$2
next to convertor tank	00-356603		pipe covering	OHA	12 ft. 4 in. 0.	D. PL	27 111	\$107	\$67	\$1
next to convertor tank	00-356603		pipe covering	OHA	12 ft. 8 in. 0.		27 111	\$170	\$121	\$2
next to mash tub	00-356603		pipe covering	AHO	7 ft. 8 in. 0.	D. PL	27 111	\$99	\$71	\$1
next to mash tub	00-356603		pipe covering	OHA	40 ft. 4 fn. 0.		27 111	\$357	\$223	\$5
next to adjunct cooker	00-356603	30%	pipe covering	OHA	12 ft. 4 in. 0.	D. PL	27 111	\$107	\$67	\$1

AREA COMMENTS The materials are in good condition with minor contact damage. The materials are approximately 1' to 12'

from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

********** AREA NUMBER: 06	AREA DESCR	IPTIO	N: 4th floor-Part #21-Grain Hop	per Roo	n	AREA AVE	RAGE	X ASBE	stos	: 427	{	****	***
LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	YTITHAUP	UNITS O	•	PIPE ID	EXP POT		RENOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
along south & east walls	00-356608	50%	pipe covering	OMA	4 1	t. 4 in.	0.0.	KPS/R	27	111	\$36	\$22	\$58
along south & east walls	00-356608		pipe covering	OMA		t. 6 in.						\$178	\$464
along south & east walls	00-356608	50%	pipe covering	OMA		t. 12 in						\$1,693	\$3,89
closet next to south doorway-at ceiling	00-356608	50%	pipe covering	OHA	5 1	t. 6 in.	0.D.	HPS/R	27	Ш	\$65		\$10
closet west of elevator	00-356608	50%	pipe covering	OHA		t. 6 in.				111		\$81	\$21
south wall-above exit & elevator	00-356608	50%	pipe covering	OHA		ft. 6 in.				111	\$260	\$162	\$42
east center area-next to east wall	00-356612	0%	wrapped cardboard/paper pipe	AHO		ft. 6 in.]		
along south & east walls	00-356730	40%	pipe covering	OHA	90 1	ft. 12 in	. 0.0	DU	27	Ш	\$1,982	\$1,524	\$3,50

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 49

ASBESTOS ASSE. - SURVEY

H-K Building W: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89

Inspector: TIM SWARTZ

Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

along south & east walls	19-356731 19-356732	50% mjp on pipe covering	OHA	4 12 in. 0.D.	DW	27 111 27 111	\$303	\$190	\$493
along south & east walls	19-356733 22-356609	0% mjp on pipe covering	OMA .	6 6 in. O.D.		27 111 27 111	\$232	\$136	\$368
along south & east walls	22-356609 22-356610 22-356611	0% mjp on pipe covering 60% 10%	OHA	4 12 in. 0.D.	HPS/K	27 111 27 111 27 111	\$303	\$190	\$493

AREA COMMENTS

AREA # 06 TOTAL \$5,799 \$4,217 \$10,016

The materials are in good condition with minor contact and water damage. The materials are approximately 1° to 16° from the floor. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a low traffic area.

****	AREA NUMBER: 07	AREA DESCRIPTION: 5th Floor-Part #21				AREA AVERAGE	ξ	******				
LOCATION OF	THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL
southwest area-by southeast corner southwest area-by		00-356613 00-356617 23-356614 23-356615 23-356616	10%	pipe covering wrapped cardboard/paper pipe mjp on pipe covering	OHA OHA OHA	8 ft. 4 in. O.D. 12 ft. 6 in. O.D. 2 4 in. O.D.		27 27 27	III III III III			\$116 \$253 \$87
southeast corner		24-356618 24-356619 24-356620		mjp on wrapped cardboard/paper	OMA	2 6 in. O.D.	DW	27 27		\$77	\$45	\$127

AREA COMMENTS

AREA # 07 TOTAL \$360 \$218 \$578

The materials are in good condition with minor contact and water damage. At a minimum, it is recommended that the materials be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a low traffic area.

******* AREA NUMBER: 08 AREA DESCRIPTION: Ground Floor					AREA AVER	ξ	****				
LOCATION OF THE MAYERIAL	SAMPLE NUMBER ASB	MATERIAL DESCRIPTION	O&M CODE	YTITHAUP	UNITS OF MEASURE	PIPE 1D		PL	REHOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
spent grain room-south wall south stairwell-at ceiling stock cellar H-against east wall	03-356469 0%	pipe covering pipe covering pipe covering	OHA OHA OHA	6 1	t. 12 in. t. 12 in. t. 12 in.	O.D RS/R	12 12 12 12	VI VI	\$330 \$132 \$881		\$58 \$23 \$1,55

HALL-KIMBRELL ENVIRONMENTAL INC.

age 50

ASSESTOS ASSE.

H-K Building #: 21

Project Number: 0980193E

Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/21/89 Inspector: TIM SWARTZ Building Number: 21/22

Building Name: BREWHOUSE/STOCK CELLARS

SEATTLE, WASHINGTON

Building Type: BREW/STOCK

Year Constructed: 1948

	03-356471 6X		12 IV			
	* *	,				
AREA COMMENTS			AREA # 08 TOTAL	\$1,343	\$1,033	\$2,376

AREA COMMENTS

The material is in good condition. The material is approximately 9' from the floor. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a high traffic area.

***** ***** AREA NUMBER: 09 AREA DESCRIPTION: 2nd Floor AREA AVERAGE % ASBESTOS: %

LOCATION OF THE MATERIAL	SAMPLE Number	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT	REHOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
north brew kettle south brew kettle mezzanine level-whirlpool tank	00-99999 00-999999 00-999999	X	boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB	180 sq.ft. 180 sq.ft. 630 sq.ft.			\$5,085 \$5,085 \$17,798	\$4,073 \$4,073 \$14,257	\$9,158 \$9,158 \$32,055

AREA COMMENTS

AREA # 09 TOTAL \$27,968 \$22,403 \$50,371

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area. This material has a stainless steel covering.

**** AREA NUMBER: 10 AREA DESCRIPTION: 3rd floor-Tank Top Room AREA AVERAGE % ASBESTOS: %

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	CODE		UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
mash tub adjunct cooker convertor tank caustic tank	00-999999 00-999999 00-999999 00-999999	X X	boiler/tank insulation boiler/tank insulation boiler/tank insulation boiler/tank insulation	OMB OMB OMB OMB	152 sc 152 sc 152 sc 152 sc	i.ft.				\$4,294 \$4,294 \$4,294 \$4,294	\$3,440 \$3,440 \$3,440 \$3,440	\$7,734 \$7,734 \$7,734 \$7,734

AREA COMMENTS

AREA # 10 TOTAL \$17,176 \$13,760 \$30,936

The material has a metal covering, making sample collection impossible. At a minimum, it is recommended that the material be maintained and monitored. If removal is planned, extensive gross removal procedures are recommended. This appears to be a high traffic area.

> BUILDING # 21 TOTAL \$231,255 \$176,138 \$407,393

HALL-KIMBRELL ENVIRONMENTAL INC.

Page 51